

TEMPORARY CHANGE T-1 to ELECTRONICS FIELD CHANGE BULLETIN 6-R-390A/URR-
NAVSHIPS 0967-063-2110.

An error appears in the Field Change Bulletin for Field Change 6-R-390A/URR, NAVSHIPS 0967-063-2110. Activities installing this field change should make the following corrections to the bulletin and temporary correction prior to accomplishment:

Delete reference to "Pin 4" of XV801 and XV802. Insert "Pin 3" in lieu of "Pin 4."
On page 3 of bulletin, page 8(a) and (b):
On page 1 of Correction T-2, line "Page 45, Fig. 28."
On page 2 of Correction T-2, line "Page 178, Fig. 89."

This correction material appeared in EIB 702 dated 13 March 1967.

17 NOV 1969
SHIPYARD TECHNICAL LIBRARY
(CODE 246-P)
PEARL HARBOR NAVAL SHIPYARD
BOX 400
FPO SAN FRANCISCO 96610