

TEMPORARY CHANGE T-2 to ELECTRONICS FIELD CHANGE BULLETIN
(EFCB) for 6-R-390A/URR Radio Receiver, NAVSHIPS 0967-063-
2110. *copy #2*

This Temporary Change contains information originally published as separate articles (EFCB Corrections) in the Electronics Information Bulletin, (EIB), number: 732.

The instructions, described herein, for making these changes shall be followed only if they have not been previously accomplished at the time the EIB, in which the information appeared, was received.

The purpose of this Temporary Change is to assure that publications drawn from stock, subsequent to publication of this information in the EIB, can be corrected.

Insert this Temporary Change in the EFCB immediately behind the front cover and preceding the title page or preceding the latest change or correction in effect.

Make pen-and-ink corrections or changes to the EFCB as follows:

Page 4, Step 16: After accomplishment of Field Change 6-R-390A/URR, check and readjust the IF Gain adjust (R519) as required.

Refer to NAVSHIPS 0967-063-2010 (formerly NAVSHIPS 95053) para. 73, page 114, for procedure.

24 NOV 1969

SHIPYARD TECHNICAL LIBRARY
(CODE 246-P)
PEARL HARBOR NAVAL SHIPYARD
BOX 430
APO SAN FRANCISCO 96610